

**TO WHOM IT MAY CONCERN**

**STRUCTURE STABILITY CERTIFICATE/SAFETY CERTIFICATE FOR  
THE BUILDING OF SAI BLITE INTERNATIONAL SCHOOL, VILLAGE  
ANJI CHAMARA DHARAMPUR TEHSIL AND DISTT SOLAN HP.**

The Sai Blite International School Village anji Chamara Dharampur Tehsil and Distt. Solan vide his office letter No. Nil dated Nil, applied for issue of structural stability / safety certificate and this stability certificate is hereby issued on the basis of the documents submitted by the applicant i.e. affidavit and structural stability/safety certificate issued on dated 30.07.2022., by Er. Rohit Thakur civil Engineer TCP Reg No. A (a) 332 District, as well as report submitted by the Assistant Engineer HP.PWD., Sub-Division Subathu vide his office letter No. PW-SSD/NOC/2022-23-915 dated 20.09.2022. On visual inspection the School building seems to be safe and fit as on today to run the School in the campus. This certificate is issued subject to the condition that the applicant shall take all necessary safety measures as required under various Acts/rules from time to time. The certificate is valid for Five years from date of issue.

Executive Engineer  
HP.PWD., Division  
E & R Division, HP.PWD  
Kasauli.

No. PW/Ksli/CB/WA/NOC-Bldg-SSSC/2019-20-10380-81 Dated:- 20.09.2022

Copy to the Sai Blite International School Anji Chamara .  
Dharampur Tehsil and Distt. Solan for information and necessary action w. r. to his  
office letter No. mentioned as above.

Copy to the Assistant Engineer HP.PWD., Sub-Division Subathu  
for information w. r. to his office letter No. mentioned as above.

Executive Engineer,  
HP.PWD., Division  
Kasauli.